



## IMPORTANT AIRWORTHINESS INFORMATION

### TO WHOM IT MAY CONCERN

Prague 27. March 2009

Light Aircraft Association of the Czech Republic acting as the Competent Authority for the microlights in the Czech Republic would like to inform You that on 21. March 2009 there was an accident of microlight aircraft UFM13 Lambáda.

At speed around 190km/h there was probably flutter at the empennage which ended by broken fuselage in the empennage part. The crew used integrated ballistic recovery system and landed without injuries.

Because of this accident the Chief Technical Office of the LAA ČR Mr. Václav Chvála ordered the manufacturer Urban Air s.r.o to issue Mandatory Bulletin which require to perform inspection checks and introduces limitation of  $V_{NE}$ . See enclosed bulletin UFM – 13 – 1/2009.

It is the duty of Urban Air to inform the owners of concerned aircraft, but we would like to inform You as well in order to assure safe operation of Lambáda aircraft.

The investigation is performed by Czech Air Accidents Investigation Institute. For further information on the progress of the investigation You can contact Mr. Strihavka at [strijavka@uzpln.cz](mailto:strijavka@uzpln.cz)

In behalf of LAA ČR Chief Technical Officer Mr. Václav Chvála

Best regards

Jan Fridrich  
Vice President LAA ČR  
Foreign affairs, industry and internal audit  
Ke Kablu 289, 102 00 Praha 10, Czech Republic  
Tel: +420 777 813 040 Fax: +420 271 085 596  
E-mail: fridrich@laacr.cz , [www.laacr.cz](http://www.laacr.cz)

Enclosure: Mandatory Bulletin – 13 – 1/2009