

**An:** <[SkyrangerClub@yahoogroups.com](mailto:SkyrangerClub@yahoogroups.com)>, <[skyranger@yahoogroups.com](mailto:skyranger@yahoogroups.com)>

**Betreff:** [skyranger] Seat belt buckle

**Antwort an:** [skyranger@yahoogroups.com](mailto:skyranger@yahoogroups.com)

Just had a problem reported to us: A seat belt buckle has failed from corrosion and snapped in two. The corrosion occurred on the 'tongue' side where the seat belt webbing wraps around, and broke on the corners where the bar emerges from the side of the webbing.

The corrosion should be quite easy to see - but of course this is not a part we perhaps pay much attention too looking for this stuff.

Can I ask everyone to check theirs please and let me know if they find any corrosion in this are so we can get a feel for whether this is particularly isolated or not.

BMAA here in UK have been informed.